MACHINE DRAWING THROUGH CAD

LAB MANUAL

Year	:	2018 - 2019
Subject Code	:	AME105
Regulations	:	IARE-R16
Class	:	III Semester
Branch	:	ME

Prepared By

Mr. G.V.R. Seshagiri Rao, Associate Professor

Mr. M. Sunil Kumar, Assistant Professor



MECHANICAL ENGINEERING

INSTITUTE OF AERONAUTICAL ENGINEERING

(Autonomous) Dundigal, Hyderabad - 500 043

2	0 0 0	
EDUCAT	ARE A	NO

NSTITUTE OF AERONAUTICAL ENGINEERING

(Autonomous) Dundigal, Hyderabad – 500 043, Telangana

Certificate

This is to certify that	Mr. / M	ls	
bearing roll no	_of B.	Tech	semester
		bi	ranch has
satisfactorily completed_		labo	oratory during
the academic year			
Signature of HOD		Sig	nature of Faculty
Signature of Internal Examiner		Signature	e of External Examiner
			,



INSTITUTE OF AERONAUTICAL ENGINEERING

(Autonomous) Dundigal, Hyderabad - 500 043

	Program Outcomes
PO1	Engineering Knowledge: Capability to apply knowledge of Mathematics, Science Engineering in the
	field of Mechanical Engineering
PO2	Problem Analysis: An ability to analyze complex engineering problems to arrive at relevant conclusion
	using knowledge of Mathematics, Science and Engineering.
PO3	Design/ Development of solution: Competence to design a system, component or process to meet
	societal needs within realistic constants.
PO4	Conduct investigation of complex problems: To design and conduct research oriented experiments as
	well as to analyze and implement data using research methodologies.
PO5	Modern Tool usage: An ability to formulate, solve complex engineering problems using modern
	engineering and information technology tools.
PO6	The Engineer society: To utilize the engineering practices, techniques, skills to meet needs of health,
	safety legal, cultural and societal issues.
PO7	Environment and Sustainability: To understand the impact of engineering solution in the societal
	context and demonstrate the knowledge for sustainable development.
PO8	Ethics: An understanding and implementation of professional and Ethical responsibilities.
PO9	Individual Team work: To function as an effective individual and as a member or leader in multi-
	disciplinary environment and adopt in diverse teams.
PO10	Communication: An ability to assimilate, comprehends, communicate, give and receive instructions to
	present effectively with engineering community and society.
PO11	Project Management and Finance: An ability to provide leadership in managing complex engineering
	project at multi-disciplinary environment and to become a professional engineer.
PO12	Life-Long learning: Recognition of the need and an ability to engage in lifelong learning to keep abreast
	with technological changes.
	Program Specific Outcomes
PSO1	Professional Skills: To produce engineering professional capable of synthesizing and analyzing
	mechanical system including allied engineering streams.
PSO2	Design/ Analysis: An ability to adapt and integrate current technologies in the design and manufacturing
	domain to enhance the employability.
PSO3	Successful Career and Entrepreneurship: To build the nation by imparting technological inputs and
	managerial skills to become a technocrats.

ATTAINMENT OF PROGRAM OUTCOMES AND PROGRAM SPECIFIC OUTCOMES

Week No.	Experiment	Program Outcomes Attained	Program Specific Outcomes Attained
1	Conventional representation	PO1, PO2, PO3, PO5	PSO1, PSO2
2	Sectional views	PO1, PO2, PO3, PO5	PSO1, PSO2
3	Dimensioning	PO1, PO2, PO3, PO5	PSO1, PSO2
4	Working drawings	PO1, PO2, PO3, PO5	PSO1, PSO2
5	Machine elements	PO1, PO2, PO3, PO5	PSO1, PSO2
6	Keys and cotter joints	PO1, PO2, PO3, PO5	PSO1, PSO2
7	Riveted joints	PO1, PO2, PO3, PO5	PSO1, PSO2
8	Couplings	PO1, PO2, PO3, PO5	PSO1, PSO2
9	Bearings	PO1, PO2, PO3, PO5	PSO1, PSO2
10	Assembly drawings-Engine parts : Stuffing box	PO1, PO2, PO3, PO5	PSO1, PSO2
11	Assembly drawings : Connecting rod and eccentric	PO1, PO2, PO3, PO5	PSO1, PSO2
12	Assembly drawings: Screw jack	PO1, PO2, PO3, PO5	PSO1, PSO2
13	Assembly drawings: Machine vice and tailstock	PO1, PO2, PO3, PO5	PSO1, PSO2
14	Assembly drawings Rams-bottom Safety Valve, feed check valve	PO1, PO2, PO3, PO5	PSO1, PSO2

INDEX

Ex.No	Date	Name of the Experiment	Page	Staff Signature
			No	
1				
2				
3				
4				
5				
5				
6				
7				
1				
8				
٥				
3				
10				

INDEX

Ex.No	Date	Name of the Experiment	Page	Staff Signature
			No	
11				
12				
13				
14				

Signature of Faculty – in-charge

MACHINE DRAWING THROUGH CAD LABORATORY

Cou	rse Code Category Hours / Week Credits		Maximum Mar						
A	ME105	Core	L	Т	Р	С	CIA	SEE	Tota
Contact	Classes Nil	Testavial Classos: Nil	- T	-		2	30 Tot	70	100
Contact Classes; Mi Tutorial Classes; Mi Fractical Classes; 42 Total Classes; 42						:5. 74			
 The course should enable students to I. Understand Code of drawing practice as per BIS conventions for mechanical elements using AutoCAD. II. Practice the drawing methods for sectioning of joints, couplings, bearings, keys. III. Prepare assembly drawings, sectional views and bill of materials for selected assemblies. 									
		LIST O	FEX	ERCI	SES				
Week-1	CONVENTIO	DNAL REPRESENTAT	TION						
Conventio bolts, keys	nal representati , gears, webs a	ion of materials, commor nd ribs; Introduction to A	n mach	nine ele AD.	ements a	nd parts suc	ch as sci	rews, nut	3,
Week-2	SECTIONAL	. VIEWS					_		
Types of s not usually	ections, selection selection sectioned.	on of section planes and	drawir	ng of se	ections a	nd auxiliary	y section	nal views	, parts
Week-3	DIMENSION								
Methods of curved and	f dimensioning l tapered featur	, general rules for sizes, es.	and pl	aceme	nt of din	nensions for	r holes,	centers, a	nd
Week-4	WORKING I	DRAWINGS							
Types of c	lrawings–worki	ng drawings for machine	e parts.						_
Week-5	MACHINE E	LEMENTS							
Drawing of following bolts, nuts	f machine elem machine eleme , stud bolts.	nents and simple parts; So nts and parts with every of	electio drawir	n of oi 1g prop	thogona portion, j	l views and popular forr	additions of sc	nal views rew threa	for the ds,
Week-6	KEYS AND (COTTER JOINTS							
Keys, cott	er joints, and ki	nuckle joint.							
Week-7	RIVETED JO	DINTS							
Riveted jo	ints for plates.		_		_		_	_	
Week-8	COUPLINGS	5							
Shaft coup	oling and spigot	joint.							
Week-9	BEARINGS								
Journal, pi	vot, and collar	bearing.							
Week-10	ASSEMBLY	DRAWINGS-ENGIN	E PAI	RTS					

Assembly drawings for the following, using conventions and parametric drawing practice: Engine parts, stuffing box.

Week-11 CONNECTING ROD AND ECCENTRIC

Eccentrics, I.C. engine connecting rod.

WeeK-12 SCREW JACK

Screw jack.

Week-13 TAIL STOCK AND MACHINE VICE

Machine vice and tailstock.

Week-14 SAFETY VALVES

Rams-bottom Safety Valve, feed check valve.

Text Books:

- 1.K.L. Narayana, P. Kannaiah, K. Venkata Reddy, "Machine Drawing", New Age Publishers, 3rd Edition, 2012.
- 2. K.C. John, "Text book of Machine Drawing", PHI Eastern Economy, 1st Edition, 2010.
- 3. P.S Gill, "Machine Drawing", S.K Kataria & Sons, 1stEdition, 2013.
- 4. Junnarkar N.D, "Machine Drawing", Pearson Edu, 1st Edition, 2007.
- 5. Basudeb Bhattacharya, "Machine Drawing", Oxford University Press, 1st Edition, 2011.
- 6. N. D. Bhatt, V. M Pancahal, "Machine Drawing", Charotar, 2014.
- 7. R. K. Dhavan, "A Text book of Machine Drawing", S.Chand Publication & Co, New Delhi, 2nd Edition 2008

Web References:

- 1. http://web.iitd.ac.in/~achawla/public_html/201/sheets/sheet5/sheet5.pdf
- 2. https://drive.google.com/file/d/0B_GCh7LMfHf6Z0VNWTNHU3pMSTg/view?pref=2&pli=1
- 3. http://www.uiet.co.in/downloads/20140911122818-Machine20Drawing.pdf
- 4. http://listpdf.com/ma/machine-drawing-book-pdf.html

Course Home Page:

SOFTWARE AND HARDWARE REQUIREMENTS FOR A BATCH OF 36 STUDENTS:

SOFTWARE: System Software: Microsoft Windows 7. Application Software: AutoCAD.

HARDWARE: 36 numbers of Desktop Computer Systems

DESIGNATION AND RELATIVE POSITIONS OF VIEWS

An object positioned in space may be imagined as surrounded by six mutually perpendicular planes. So, for any object, six different views may be obtained by viewing at it along the six directions, normal to these planes. Figure 1.0 shows an object with six possible directions to obtain the different views which are designated as follows:

View in the direction $\mathbf{a} =$ view from the front

View in the direction $\mathbf{b} =$ view from above



Fig. 1.0 View in the direction c = view from the left

View in the direction d = view from the right

View in the direction e = view from below

View in the direction f = view from the rear

Figure 1.1 a shows the relative positions of the above six views in the first angle projection and Fig.1.1 b, the distinguishing symbol of this method of projection. Figure 1.2 a shows the relative position of the views in the third angle projection and Fig. 1.2b, the distinguishing symbol of this method of projection



Fig. 1.1

Fig. 1.2

TYPES OF LINES

Illustration	Application
Thick	Outlines, visible edges, surface boundaries of objects, margin lines
Continuous thin	Dimension lines, extension lines, section lines leader or pointer lines, construction lines, boarder lines
Continuous thin wavy	Short break lines or irregular boundary lines – drawn freehand
Continuous thin with zig-zag	Long break lines
Short dashes, gap 1, length 3 mm	Invisible or interior surfaces
Short dashes - · - · - · - · - · - · - · - · q	Center lines, locus lines Alternate long and short dashes in a proportion of 6:1,
Long chain thick at end and thin elsewhere	Cutting plane lines

WEEK-I - CONVENTIONAL REPRESENTATION

Туре	Convention	Material
Metals		Steel, Cast Iron, Copper and its Alloys, Aluminium and its Alloys, etc.
		Lead, Zinc, Tin, White-metal, etc.
Glass	Yh. Yh. Yh.	Glass
		Porcelain, Stoneware, Marble, Slate, etc.
Packing and Insulating material		Asbestos, Fibre, Felt, Synthetic resin products, Paper, Cork, Linoleum, Rubber, Leather, Wax, Insulating and Filling materials, etc.
Liquids		Water, Oil, Petrol, Kerosene, etc.
Wood		Wood, Plywood, etc.
Concrete		A mixture of Cement, Sand and Gravel

Exercise No. 1 Conventional Representation of Materials

Title Subject Convention Splined shafts Interrupted views _____ Semi-elliptic 1 leaf spring Semi-elliptic leaf spring with eyes Diagrammatic Subject Convention Representation Cylindrical compression spring Cylindrical tension spring

Exercise No. 2 Conventional Representation of Common Machine Elements

(b)

Exercise No. 3 Conventional	Representation	of Machine	Parts
------------------------------------	----------------	------------	-------

Title	Subject	Convention
Straight knurling		
Diamond knurling		
Square on shaft		
Holes on circular pitch		
Bearings		
External screw threads (Detail)		♦ 🖽
Internal screw threads (Detail)		
Screw threads (Assembly)		

(c)



Exercise No. 4 Conventional Representation Of Screws.







HEXAGONAL HEADED BOLT WITH NUT AND WASHER





Exercise No. 6 Conventional Representation of Webs and Ribs

RIB





Exercise No. 7 Introduction to AutoCAD Commands

Command	Keystroke	lcon	Menu	Result
Line	Line / L	/	<u>D</u> raw > <u>L</u> ine	Draw a straight line segment from one point to the next
Circle	Circle / C		<u>D</u> raw > <u>C</u> ircle > Center, <u>R</u> adius	Draws a circle based on a center point and radius.
Erase	Erase / E		<u>M</u> odify > <u>E</u> rase	Erases an object.
Print	Print / Plot Cntl+P	B	<u>F</u> ile > <u>P</u> rint	Enables the Print/Plot Configuration Dialog Box
Undo	U (Don't use 'Undo' for now)	•	<u>E</u> dit > <u>U</u> ndo	Undoes the last command.
Rectangle	RECTANGLE / REC		<u>D</u> raw > Rectangle	Draws a rectangle after you enter one corner and then the second.
Multi Lines	MLINE / ML	No Icon	<u>D</u> raw > <u>M</u> ultiline	Draw parallel lines based on the parameters you define.
Trim	TRIM / TR	-/	<u>M</u> odify > <u>T</u> rim	Trims objects to a selected cutting edge.
Extend	EXTEND / EX	/	<u>M</u> odify > Extend	Extends objects to a selected boundary edge.
Offset	OFFSET / O	æ	<u>M</u> odify > Off <u>s</u> et	Offsets an object (parallel) by a set distance.
Object Snaps	OSNAP / OS / F3	CLICK OSNAP	<u>T</u> ools > Object S <u>n</u> ap Settings	Brings up the OSNAP dialog box.

ICON	SETTING	ICON	SETTING
------	---------	------	---------

<u>_</u>	Endpoint		Perpendicular
¥	Midpoint	Ó	Tangent
\bigcirc	Center	Fo	Nearest
0	Node	×	Apparent Intersection
\bigcirc	Quadrant	//	Parallel
×	Intersection	Ø.	None
	Extension	n.	Osnap Setting
	Insertion Point	— 0	Temporary Tracking Point
			Snap From

RIGHT TO LEFT	CROSSING SELECTION	GREEN (with a dotted outline	SECLECTS ANY OBJECT THAT EITHER CROSSES THE BOUNDARY OR IS INSIDE IT
LEFT TO RIGHT	WINDOW SELCTION	BLUE	SELECTS ON OBJECTS THAT ARE COMPLETELY WITHIN THE BOX

Command	Keystroke	Icon	Menu	Result
Move	Move / M	4	<u>M</u> odify > Mo <u>v</u> e	Moves an object or objects
Сору	Сору / СР	SS	<u>M</u> odify > Cop <u>y</u>	Copies object(s) once or multiple times
Stretch	Stretch / S		<u>M</u> odify > Stretc <u>h</u>	Stretches an object after you have selected a portion of it
Mirror	Mirror / MI	4	<u>M</u> odify > Mirror	Creates a mirror image of an object or selection set
Rotate	Rotate / RO	(3)	<u>M</u> odify > <u>R</u> otate	Rotates objects to a certain angle
Fillet	Fillet / F	~	<u>M</u> odify > <u>F</u> illet	Creates a round corner between two lines
Chamfer	Chamfer / CHA	7	<u>M</u> odify > <u>C</u> hamfer	Creates an angled corner between two lines
Array	Array / AR		<u>M</u> odify > <u>A</u> rray	Creates a repeating pattern of the selected objects
Layer	Layer / LA		<u>F</u> ormat > <u>L</u> ayer	Starts the Layer and Linetype property dialog box
Text	Text	No Icon	<u>D</u> raw > Single Line Te <u>x</u> t	Creates a single line of text
Dimension	Dim	Many	Dimension > (pick one)	Dimensions previously drawn objects
Scale	Scale / SC		<u>M</u> odify > Scale	Proportionately resizes (or scales) objects

COMMAND OPTION	ICON	DESCRIPTION
Zoom <u>A</u> ll	Q	This option causes AutoCAD to display the whole drawing as far as its drawing limits (whichever is the greater of the two).
Zoom <u>C</u> enter	R	This option requires two things: a point that is to be the <u>center</u> of the new display and a value to be its <u>new height</u> <i>in drawing units</i> . The existing height is the default for the new height to allow for panning across the drawing. If the new height value is followed by "X" (eg. 2x), then it is taken as a magnification factor relative to the current height. If followed by "XP", then it is taken as a scale factor relative to paper space and can be used for scaling the contents of paper space viewports.
Zoom <u>D</u> ynamic		This is a very useful ZOOM option once it is understood. It permits very quick movement around the drawing. Once selected, this option redraws the graphics area of the screen and displays two rectangles. The larger box shows the extents of the current drawing. The smaller box shows the current view with an "X" in the middle. This moves with the mouse. This view box should be positioned so that its lower left corner is at the lower left corner of the view required. By pressing the left button on the mouse, the "X" is replaced by an "> " pointing to the right side of the view box. This allows you to change the magnification. As the mouse is moved, the view box shrinks and expands so that the size of the required view can be set. The left mouse button toggles between PAN "X" and ZOOM "> " mode so that fine adjustments can be achieved. When the view required has been selected, press <enter> or right click to cause AutoCAD to display it.</enter>
Zoom <u>E</u> xtents	Ð	This option will display all the graphics that are contained in the drawing (referred to as the <i>drawing extents</i>) with the largest image possible.
Zoom Previous	Ľ	This option restores the displayed view prior to the current one. For the purpose of this option, up to 10 views are saved so that the last ten views can be recalled. This option includes every time you use the scroll bar, which is one reason to avoid the scroll bars for panning a lot in your drawing.
Zoom <u>S</u> cale	R	This is a 'hidden' default option. You do <u>not</u> have to type "S" to choose this option. It simply requires the entry of a number that represents a magnification factor. Note that the factor is applied to the entire drawing (as defined by the drawing's limits). Numbers less than 1 will reduce the displayed size of the drawing, while numbers greater than 1 will enlarge it. If "X" is inserted after the number (eg. 0.8x) then the factor is applied <i>to the current view</i> . If "XP" is inserted after the scale factor, then the view is scaled relative to paper space. This is useful for zooming a view within a paper space viewport to a specific scale, for example, "1/48XP" will produce a view of model space at a scale of $\frac{1}{4}$ " = 1' relative to paper space.

COMMAND OPTION	ICON	DESCRIPTION	
Zoom <u>W</u> indow		This option (also a 'hidden' default) prompts the user to pick two corners of a box on the existing view in order to enlarge that area to fill the display.	
Zoom <u>R</u> ealtime	Q [±]	Zoom Real time provides interactive zooming capability. Pressing <enter> (after entering zoom) on the command line automatically places you in Real time mode. Hold the left mouse button down at the midpoint of the drawing and move the cursor vertically to the top (positive direction) of the window to zoom in up to 100% (2x magnification). Hold the left mouse button down at the midpoint of the drawing and move the cursor vertically to the top of the window to zoom out to 100% (.5x magnification). You cannot zoom out beyond the extents of the current view.</enter>	
		When you release the pick button, zooming stops. You can release the pick button, move the cursor to another location in the drawing, and then press the pick button again and continue zooming from that location. To exit Real time Zoom mode, press <enter> or (ESC).</enter>	
Aerial View command: DSVIEWER	None	Aerial View is a zooming tool that displays a view of the drawing in a separate window so that you can quickly move to that area. If you keep the Aerial View window open as you work, you can zoom and pan without choosing a menu option or entering a command. You can change the view by creating a new view box in the Aerial View window. To zoom in to the drawing, make the view box smaller by left clicking a rectangle. To zoom out of the drawing, make the view box larger. As you zoom in or out of the drawing, a real-time view of the current zoom location is displayed in the graphics area. The screenshot shows how the view box looks. Right click in the box and you can move the box to where you want to zoom to.	
Zoom <u>O</u> bject	Q	This option asks you to select an object or objects, then press <enter> and the screen will zoom to those objects only. This is great for when you want to work on object.</enter>	
Zoom In	Ð	Clicking this icon will zoom in to the drawing by about 50%. This option is only available as an icon and cannot be invoked by the command line.	
Zoom Out		Similar to 'Zoom In' - this icon will zoom out of your drawing and allow you to see about 50% more of your drawing space.	
Mouse Scroll	-	If you have a scrolling wheel on your mouse, you can use it to zoom in and out of your drawing. Scroll towards you to zoom out and away from you to zoom in. You have the option to change the amount of zoom per wheel click with the Zoom factor system variable. Keep in mind that you will zoom in and out using your mouse location as a 'centre point'.	

COMMAND OPTION	ICON	DESCRIPTION
PAN	*	Panning allows you to quickly move around the drawing area at the same magnification you currently have set. Type in PAN (or P) <enter> and a hand will appear on the screen. Left click and hold to move around your drawing.</enter>

Command	Keystroke	Icon	Menu	Result
Boundary Hatch	Bhatch / H		Draw > Hatch	Covers an area with a predefined pattern
Hatch Edit	HatchEdit / HE		Modify > Object > Hatch	Edits an existing Hatch



WEEK-II SECTIONAL VIEWS

Orthographic views when carefully selected may reveal the external features of even the most complicated objects.

However, there are objects with complicated interior details and when represented by hidden lines, may not effectively

reveal the true interior details. This may be overcome by representing one or more of the views 'in section'.

A sectional view is obtained by imagining the object, as if cut by a cutting plane and the portion between the observer and the section plane being removed. Figure. 1 (*a*) shows an object, with the cutting plane passing through it and Fig. 1(b), the two halves drawn apart, exposing the interior details.



Fig.1.0 Principles of sectioning

In order to show such features clearly, one or more views are drawn as if a portion had been cut away to reveal the interior This procedure is called sectioning and the view showing the cut away picture is called section view. A section is an imaginary cut taken through an object to reveal the shape or interior construction.

Fig. 2a shows the imaginary cutting plane in perspective view.

The imaginary cutting plane is projected on a standard view so that the sectional view with orthographic representation is obtained as shown in Fig. 2 b.

A sectional view must show which portions of the object are solid material and which are spaces. This is done by section lining (cross-hatching) the solid parts with uniformly spaced thin lines generally at 45°.





(a)

Fig. 2 sectional view

(b)

Types of Sections

Depending on the number of cutting planes, sectional views can be simple with one cutting plane (Fig. 3) or complex with two or more cutting planes (Fig.4).

If the cutting plane-line cuts entirely across the object, it is called a full section.

If the cutting plane cuts halfway through the object, it is a half section.

In addition to these, there are broken-out sections, rotated sections, removed sections, auxiliary sections, and assembly sections.



Fig.3 sectional views can be simple with one cutting plane



Fig.4 sectional views can be complex with two or more cutting planes

Full Section

A sectional view obtained by assuming that the object is completely cut by a plane is called a full section or sectional view. shown in Fig. 5.1a, in full section. The sectioned view provides all the inner details, better than the unsectioned view with dotted lines for inner details (Fig. 5.1b). The cutting plane is represented by its trace (V.T) in the view from the front (Fig. 5.1c) and the direction of sight to obtain the sectional view is represented by the arrows.

When cutting plane passes fully through an object, it is called full section



Fig. 5 Sectioned and un-sectioned views

It may be noted that, in order to obtain a sectional view, only one half of the object is imagined to be removed, but is not actually shown removed anywhere except in the sectional view. Further, in a sectional view, the portions of the object that have been cut by the plane are represented by section lining or hatching. The view should also contain the visible parts behind the cutting plane.



Figure.6 Full Sectional View

Half Section

A half sectional view is preferred for symmetrical objects. For a half section, the cutting plane removes only one quarter of an object. For a symmetrical object, a half sectional view is used to indicate both interior and exterior details in the same view.

A half section is made by cutting halfway through an object (Fig. 7). Thus, one half is drawn in section and the other half is a side view, usually, hidden lines are not used (inside details are visible on the section view).



Fig. 7 Half Section

Auxiliary sections may be used to supplement the principal views used in orthographic projections. A sectional view projected on an auxiliary plane, inclined to the principal planes of projection, shows the cross-sectional shapes of features such as arms, ribs and so on. In Fig.8, auxiliary cutting plane X-X is used to obtain the auxiliary section X-X



Fig. 8 Auxiliary section

Assembly Sections

Assembly sections consist of a combination of parts.

The purpose of an assembly section is to reveal the interior of a machine or structure so that the separate parts can be clearly shown and identified. However, the separate parts do not need to be described. In assembly drawing, only such hidden details (as needed for part identification or dimensioning) are drawn.



Fig. 9 Assembly section

Hidden Edges and Surface in Section

Sections are primarily used to replace hidden lines with visible lines. As a rule, hidden lines and surfaces should be omitted in sectional views.

Thus, preferred sectional view should be as in Fig. 10.

In some cases, hidden edges and surfaces can be shown for describing the object



Fig .10 Hidden Edges and surfaces in section

Section Lining (Cross Hatching)

Section lining of a cut surface is indicated by fine lines, which are drawn as continuous lines usually at an angle of 45° with uniform distance (about 2 mm). For smaller or larger areas, distance between lines can be from 1 mm to 4 mm.

Section lining or cross-hatching lines should not be parallel or perpendicular to any main visible line bounding the sectioned area.



Fig. 11 Cross Hatching

Ribs and webs are used to strengthen the parts. When the cutting plane passes through the ribs lengthwise, cross-hatching would give the misleading impression that the section was conical (Fig.12).

Therefore, cross-hatching is eliminated from the ribs and webs (as if the cutting plane was just in front of them) when the cutting plane passes longitudinally through them (Fig. 12and 13).



Fig. 12Web

Fig. 13 Ribs

SPOKES AND ARMS IN SECTION

When a cutting plane passes through pulley spokes or arms, cross-hatching is eliminated where the plane is thought

of as being just in front of the spokes.

Even though the cutting plane passes through two of the spokes in Fig. 14, the sectional view in Fig. 14 a must be made without cross-hatching the spokes in order to avoid the appearance of a solid web as in Fig. 14 b.



Fig 14 Spokes and Arms

Various cutting planes can be selected for obtaining clear sectional views

The plane may cut straight across (Fig.15) or be offset (changing direction forward and backward) to pass through features.



Fig. 15 : Various cutting planes obtaining clear sectional views.

Draw (*i*) sectional view from the front, (*ii*) the view from above and (*iii*) the view from the right of the shaft support







Draw the (i) the sectional view from the front, (ii) the view from above and (iii) the sectional view from the left Of the given Machine block.



Isometric View of Machine Block



Week-III Dimensioning

A drawing of a component, in addition to providing complete shape description, must also furnish information regarding the size description. These are provided through the distances between the surfaces, location of holes, nature of surface finsih, type of material, etc. The expression of these features on a drawing, using lines, symbols, figures and notes is called dimensioning.

BASIC DIMENSIONING

In many applications, a drawing should contain annotations showing lengths or distances or angles between objects to convey the desired information. Dimensioning is the process of adding these annotations to a drawing. AutoCAD provides four basic types of dimensioning; linear, angular, diameter and radius.

DIM and DIMI Commands—DIMI command allows executing one dimensioning command and then returns to the normal command mode. If several dimensioning commands are to be executed, DIM command should be used. In this mode, the normal set of AutoCAD commands is replaced by a special set of dimensioning commands. To end the process of dimensioning, EXIT command has to be used.

The elements of dimensioning include the projection line, dimension line, leader line, dimension line termination, the origin indication and the dimension itself. The various elements of dimensioning are shown in Figs. 1 and 2. The following are some of the principles to be adopted during execution of dimensioning:



Fig. 1 Elements of dimensioning


Fig. 2 Elements of dimensioning

Projection and dimension lines should be drawn as thin continuous lines.

Projection lines should extend slightly beyond the respective dimension lines.

Projection lines should be drawn perpendicular to the feature being dimensioned. Where necessary, they may be drawn obliquely, but parallel to each other (Fig. 2). However, they must be in contact with the feature.

Projection lines and dimension lines should not cross each other, unless it is unavoidable (Fig.4)

A dimension line should be shown unbroken, even where the feature to which it refers, is shown broken (Fig. 5).

A centre line or the outline of a part should not be used as a dimension line, but may be used in place of projection line (Fig. 6).



Fig. 4



Fig. 6

Dimension lines should show distinct termination, in the form of arrow heads or oblique strokes or where applicable, an origin indication. Two dimension line terminations and an origin indication are shown in Fig. 7.



Fig. 8

METHOD-1 (Aligned System)

Dimensions should be placed parallel to their dimension lines and preferably near the middle, above and clear-off the dimension line (Fig. 9). An exception may be made where super-imposed running dimensions are used (Fig. 15)

Dimensions may be written so that they can be read from the bottom or from the right side of the drawing. Dimensions on oblique dimension lines should be oriented as shown in Fig. 10. Angular dimensions may be oriented as shown in Fig. 11.



Fig. 10 Oblique dimensioning

Fig. 9

Fig. 11 Angular dimensioning

METHOD-2 (Uni-directional System)

Dimensions should be indicated so that they can be read from the bottom of the drawing only. Non-horizontal dimension lines are interrupted, preferably near the middle, for insertion of the dimension (Fig. 12). Angular dimensions may be oriented as in Fig. 13



Arrangement of Dimensions

The arrangement of dimensions on a drawing must indicate clearly the design purpose. The following are the ways of arranging the dimensions.

Chain Dimensions

Chains of single dimensions should be used only where the possible accumulation of tolerances does not endanger the functional requirement of the part (Fig. 14).



Fig. 14 Chain dimensioning

Parallel Dimensions

In parallel dimensioning, a number of dimension lines, parallel to one another and spaced -out are used. This method is used where a number of dimensions have a common datum feature (Fig. 15)



Fig. 15 Parallel dimensioning

Combined Dimensions

These are the result of simultaneous use of chain and parallel dimensions (Fig. 16).



Fig. 16 Combined dimensioning

Diameters

Diameters should be dimensioned on the most appropriate view to ensure clarity. The dimension value should be preceded by ϕ . Figure 17 shows the method of dimensioning diameters.



Chords, Arcs, Angles and Radii

The dimensioning of chords, arcs and angles should be as shown in Fig. 18. Where the centre of an arc falls outside the limits of the space available, the dimension line of the radius should be broken or interrupted according to whether or not it is necessary to locate the centre (Fig. 19).



50

Fig. 18 Dimensioning of chords, arcs and angles



Equi-distant Features

Linear spacings with equi-distant features may be dimensioned as shown in Fig. 20.



Fig. 20 Dimensioning equi-distant features

Tapered Features

Tapered features are dimensioned, either by specifying the diameters at either end and the length, or the length, one of the diameters and the taper or the taper angle (Fig. 21 a). A slope or flat taper is defined as the rise per unit length and is dimensioned by the ratio of the difference between the heights to its length (Fig 21 b).



Fig. 21 Dimensioning tapered features

EXAMPLES

Violations of some of the principles of drawing are indicated in Fig. 22 a. The corrected version of the same as per the BIS, SP–46: 1988 is given in Fig. 22 b and the reasons are given below:

1. Dimension should follow the shape symbol (Fig. 22).

- 2. and 3. As far as possible, features should not be used as extension lines for dimensioning.
- 4. Extension line should touch the feature.
- 5. Extension line should project beyond the dimension line.
- 6. Writing the dimension is not as per the aligned system.
- 7. Hidden lines should meet without a gap
- 8. Centre line representation is wrong. Dot should be replaced by a small dash.
- 9. Horizontal dimension line should not be broken to insert the value of the dimension
- 10. Dimension should be placed above the dimension line
- 11. Radius symbol should precede the dimension
- 12. Centre lines should cross at long dashes
- 13. Dimension should be written by symbol (not abbreviation) followed by its value
- 14. Note with dimensions should be written in capitals.
- 15. Elevation is not the correct usage.
- 16.Usage of the term "plan" is obsolete in graphic language.





b-Correct

Fig. 22

Week-IV Working Drawings

A production drawing, also known as working drawing, supplies information and instructions for

the manufacture or construction of machines or structures. A production drawing should provide

all the dimensions, limits, special finishing processes, surface quality, etc. The particulars of material, the number of components required for the assembly, etc., are given in the title block. The production drawing of a component should also indicate the sub-assembly or main assembly

where it will be assembled. Since the working drawings may be sent to other companies to make or assemble the unit, the drawings should confirm with the standards followed in the country. For this reason, aproduction drawing becomes a legal document between the parties, in case of disputes in manufacturing. Working drawings may be classified into two groups : (i) detail or part drawings and (ii) assembly drawings

Types of working Drawings

A detail or part drawing is nothing but a production or component drawing, furnishing complete information for the construction or manufacture of the part. This information may be classified as:

1. Shape description This refers to the selection of number of views to describe the shape of the part. The part may be drawn in either pictorial or orthographic projection; the latter being used more frequently. Sectional views, auxiliary views and enlarged detailed views may be added to the drawing in order to provide a clear image of the part.

2. Size description Size and location of the shape features are shown by proper dimensioning. The manufacturing process will influence the selection of some dimensions, such as datum feature, tolerances, etc.

3. Specifications This includes special notes, material, heat treatment, finish, general tolerances and number required. All this information is mostly located near the title block.

4. Additional information Information such as drawing number, scale, method of projection, date, names of the parts, the draughter's name, etc., come under additional information which is included in the title block.

Since the craftsman will ordinarily make one component at a time, it is advisable to prepare the production drawing of each component, regardless of its size, on a separate sheet. Figures 1 and 2 show the detailed drawings of a template jig and gear.



Exercise No. 18

Fig. 1 Template Jig



Fig.2 Gear



Fig. 3 Crank

Week-V MACHINE ELEMENTS

FORMS OF THREADS

Bureau of Indian Standards (BIS) adapts ISO (International Organisation for Standards) metric threads which are adapted by a number of countries apart from India.

The design profiles of external and internal threads are shown in Fig. 1. The following are the relations between the various parameters marked in the figure :



 $\begin{array}{lll} \mathbf{P} = \mathrm{Pitch} & d_3 = d_2 - 2 \ (\mathrm{H}/2 - \mathrm{H}/6) \\ \mathrm{H} = 0.86 \ \mathrm{P} & = d - 1.22 \mathrm{P} \\ \mathrm{D} = d = \mathrm{Major \ diameter} & \mathrm{H_1} = (\mathrm{D} - \mathrm{D_1})/2 = 5 \mathrm{H}/8 = 0.54 \mathrm{P} \\ \mathrm{D_2} = d_2 = d - 0.75 \mathrm{H} & h_3 = (d - d_3)/2 = 17/24 \mathrm{H} = 0.61 \mathrm{P} \\ \mathrm{D_1} = d_2 - 2(\mathrm{H}/2 - \mathrm{H}/4) = d - 2 \mathrm{H_1} & \mathrm{R} = \mathrm{H}/6 = 0.14 \mathrm{P} \end{array}$

Other Thread Profiles

Apart from ISO metric screw thread profile, there are other profiles in use to meet various applications. These profiles are shown in Fig. 5.3, the characteristics and applications of which are discussed below :

V-Thread (sharp)

This thread profile has a larger contact area, providing more frictional resistance to motion.

Hence, it is used where effective positioning is required. It is also used in brass pipe work.

British Standard Whitworth (B.S.W) Thread

This thread form is adopted in Britain in inch units. The profile has rounded ends, making it less liable to damage than sharp V-thread.

Buttress Thread

This thread is a combination of V-and square threads. It exhibits the advantages of square thread, like the ability to transmit power and low frictional resistance, with the strength of the V-thread. It is used where power transmission takes place in one direction only such as screw press, quick acting carpenter's vice, etc.

Square Thread

Square thread is an ideal thread form for power transmission. In this, as the thread flank is at right angle to the axis, the normal force between the threads, acts parallel to the axis, with zero radial component. This enables the nut to transmit very high pressures, as in the case of a screw jack and other similar applications.

ACME Thread

It is a modified form of square thread. It is much stronger than square thread because of the wider base and it is easy to cut. The inclined sides of the thread facilitate quick and easy engagement and disengagement as for example, the split nut with the lead screw of a lathe.

Worm Thread

Worm thread is similar to the ACME thread, but is deeper. It is used on shafts to carry power to worm wheels.



Fig. 5.3 Types of thread profiles

RIGHT HAND AND LEFT HAND THREADS

Screw threads may be right hand or left hand, depending on the direction of the helix. A right hand thread is one which advances into the nut, when turned in a clockwise direction and a left hand thread is one which advances into the nut when turned in a counter clockwise direction. An abbreviation LH is used to indicate a left hand thread. Unless otherwise stated, a thread should be considered as a right hand one. Figure 5.5 illustrates both right and left hand thread forms.



Fig. 5.5 Right hand and left hand threads

BOLTED JOINT

Nuts in general are square or hexagonal in shape. The nuts with internal threads engage with the corresponding size of the external threads of the bolt. However, there are other forms of nuts used to suit specific requirements. For nuts, hexagonal shape is preferred to the square one, as it is easy to tighten even in a limited space. This is because, with only one-sixth of a turn, the spanner can be re-introduced in the same position. However, square nuts are used when frequent loosening and tightening is required, for example on job holding devices like vices, tool posts in machines, etc. The sharp corners on the head of bolts and nuts are removed by chamfering.



Fig. 5.11 Bolted joint

Methods of Drawing Hexagonal (Bolt Head) Nut

Drawing hexagonal bolt head or nut, to the exact dimensions is labourious and time consuming. Moreover, as standard bolts and nuts are used, it is not necessary to draw them accurately. The following approximate methods are used to save the draughting time

Method 1 (Fig. 5.12)

Empirical relations :

Major or nominal diameter of bolt = D

Thickness of nut, T = D

Width of nut across flat surfaces, W = 1.5D + 3 mm

Radius of chamfer, R =1.5D



Fig. 5.12 Method of drawing views of a hexagonal nut (Method I)

PROCEDURE

Draw the view from above by drawing a circle of diameter, W and describe a regular hexagon on it, by keeping any two parallel sides of the hexagon, horizontal.

Project the view from the front, and the view from side, and mark the height equal to D.

With radius R, draw the chamfer arc 2-1-3 passing through the point 1 in the front face.

Mark points 4 and 5, lying in-line with 2 and 3.

Locate points 8,9 on the top surface, by projecting from the view from above.

Draw the chamfers 4–8 and 5–9.

Locate points 6 and 7, lying at the middle of the outer two faces.

Draw circular arcs passing through the points 4, 6, 2 and 3, 7, 5, after determining the radius R_1 geometrically. Project the view from the side and locate points 10, 11 and 12.

Mark points 13 and 14, lying at the middle of the two faces (view from the side).

Draw circular arcs passing through the points 10, 13, 11 and 11, 14, 12, after determining the radius R_2 geometrically.

It may be noted that in the view from the front, the upper outer corners appear chamfered.

In the view from the side, where only two faces are seen, the corners appear square.

Method 2 (Fig. 5.13)

Empirical relations:

Major or nominal diameter of bolt = D

Thickness of nut, T = D

Width of the nut across corners = 2 D

Radius of chamfer arc, R = 1.5 D

Figure 5.13 illustrates the stages of drawing different views of a hexagonal nut, following the above relations, which are self-explanatory.



Fig. 5.13 Method of drawing views of a hexagonal nut (Method II)

Method of Drawing Square (Bolt Head) Nut

A square bolt head and nut may be drawn, showing either across flats or corners. Following relations may be adopted for the purpose:

Major or nominal diameter of bolt	= D
Thickness of nut, T	= D
Width of the nut across flats, W	= 1.5 D + 3 mm
Radius of chamfer arc, R	= 2 D





Fig.5.14 Method of drawing the views of a square nut

Hexagonal and Square Headed Bolts

Figure 5.15 shows the two views of a hexagonal headed bolt and square headed bolt, with the proportions marked.



Square Headed Bolt with Square Neck

It is provided with a square neck, which fits into a corresponding square hole in the adjacent part, preventing the rotation of the bolt (Fig. 5.18).





Eye Bolt

In order to facilitate lifting of heavy machinery, like electric generators, motors, turbines, etc., eye bolts are screwed on to their top surfaces. For fitting an eye bolt, a tapped hole is provided, above the centre of gravity of the machine (Fig. 5.21).



Fig. 5.21 Eye-bolt

Stud Bolt or Stud

It consists of cylindrical shank with threads cut on both the ends (Fig. 5.22a). It is used where there is no place for accommodating the bolt head or when one of the parts to be joined is too thick to use an ordinary bolt.

The stud is first screwed into one of the two parts to be joined, usually the thicker one. A stud driver, in the form of a thick hexagonal nut with a blind threaded hole is used for the purpose. After placing the second part over the stud, a nut is screwed-on over the nut end. It is usual to provide in the second part, a hole which is slightly larger than the stud nominal diameter. Figure 5.22*b* shows a stud joint.



Fig. 5.22 (a)-Stud, (b)-Stud joint

Other Forms of Nuts

Flanged Nut

This is a hexagonal nut with a collar or flange, provided integral with it. This permits the use of a bolt in a comparitively large size hole (Fig. 5.23a).

Cap Nut

It is a hexagonal nut with a cylindrical cap at the top. This design protects the end of the bolt from corrosion and also prevents leakage through the threads. Cap nuts are used in smoke boxes or locomotive and steam pipe connections (Fig. 5.23b).

Dome Nut

It is another form of a cap nut, having a spherical dome at the top (Fig. 5.23c).

Capstan Nut

This nut is cylindrical in shape, with holes drilled laterally in the curved surface. A tommy bar may be used in the holes for turning the nut (Fig. 5.23d). Holes may also be drilled in the upper flat face of the nut.











d - Capstan nut

e - Ring nut

f - Wing nut

Fig. 5.23 Other forms of nuts



Week-VI KEYS AND COTTER JOINTS



The rectangular sunk key with head at one end is known as **GIB HEAD KEY.** The head is provided to facilitate the removal of key.

Width w = d/4

Thickness at large end t = 2w/3 = d/6



A cotter is a flat wedge shaped piece, made of steel. It is uniform in thickness but tapering in width, generally on one side; the usual taper being 1:30. The lateral (bearing) edges of the cotter and the bearing slots are generally made semi-circular instead of straight (Fig. 1.0).

This increases the bearing area and permits drilling while making the slots. The cotter is locked in position by means of a screw as shown in Fig. 1.1.

Cotter joints are used to connect two rods, subjected to tensile or compressive forces along their axes. These joints are not suitable where the members are under rotation. The following are some of the commonly used cotter joints:





Fig. 1.0 Cotter and the bearing slot

Fig. 1.1 Locking arrangement of cotter

Cotter Joint with Sleeve

This is the simplest of all cotter joints, used for fastening two circular rods. To make the joint, the rods are enlarged at their ends and slots are cut. After keeping the rods butt against each other, a sleeve with slots is placed over them. After aligning the slots properly, two cotters are driven-in through the slots, resulting in the joint (Fig. 1.1). The rod ends are enlarged to take care of the weakening effect caused by the slots.

The slots in the rods and sleeve are made slightly wider than the width of cotter. The relative positions of the slots are such, that when a cotter is driven into its position, it permits wedging action and pulls the rod into the sleeve.

Draw the sectional view from the front, and view from the side of a cotter joint with sleeve used to connect two rods of 50 mm diameter each.



Fig. 1.2 Cotter joint with sleeve

Exercise No. 26 Cotter Joint with Socket and Spigot Ends

This joint is also used to fasten two circular rods. In this, the rod ends are modified instead of using a sleeve. One end of the rod is formed into a socket and the other into a spigot (Fig1.3) and slots are cut. After aligning the socket and spigot ends, a cotter is driven-in through the slots, forming the joint.

Draw the half sectional view from the front, with top half in section and the view from the side of a cotter joint with socket and spigot ends, to connect two rods of 50 mm diameter each.



Fig. 1.3 Cotter joint with socket and spigot ends

Knuckle Joint

A knuckle joint is a pin joint used to fasten two circular rods. In this joint, one end of the rod is formed into an eye and the other into a fork (double eye). For making the joint, the eye end of the rod is aligned into the fork end of the other and then the pin is inserted through the holes and held in position by means of a collar and a taper pin (Fig. 1.4). Once the joint is made, the rods are free to swivel about the cylindrical pin.

Knuckle joints are used in suspension links, air brake arrangement of locomotives, etc.



Fig.1.4

Draw a Knuckle joint with 50 mm diameter (D)



Fig. 1.5 Knuckle joint

Week-VII Riveted Joints



Riveted Joints





Single strap chain riveted butt joint (single row)





Single riveted, double strap butt joint



Double riveted, double strap chain butt joint



Double riveted, double strap zig zag butt joint


Week-VIII Couplings

Shaft couplings are used to join or connect two shafts in such a way that when both the shaftsrotate, they act as one unit and transmit power from one shaft to the other. Shafts to beconnected or coupled may have collinear axes, intersecting axes or parallel axes at a smalldistance. Based on the requirements, the shaft couplings are classified as: (*i*) rigid couplings,(*ii*) flexible couplings, (*iii*) loose or dis-engaging couplings and (*iv*) non-aligned couplings.





Oldham's coupling



Exercise No. 29





Fig. 7.4 Flanged coupling





Solid flanged coupling

Draw (*a*) half sectional view from the front, top half in section and (*b*) view from the side of a bushed pin type flange coupling, indicating proportions to connect two shafts, each of diameter 30 mm.



Bushed pin type flanged coupling

Exercise No. 31



Universal coupling

Week-IX Bearings

Bearings are supports for shafts, providing stability, and free and smooth rotation. The importance of bearings may be understood from the supporting requirement of machine tool spindles, engine crankshafts, transmission or line shafts in workshops, etc. Bearings are broadly classified into two categories: sliding contact bearings and rolling contact bearings or antifriction bearings.

Journal Bearings





Pivot or foot-step bearing

This bearing is used to support a vertical shaft under axial load. Further, in this, the shaft is terminated at the bearing. The bottom surface of the shaft rests on the surface of the bearing which is in the form of a disc. The bush fitted in the main body supports the shaft in position and takes care of possible radial loads coming on the shaft.





Draw (*a*) sectional view from the front and (*b*) view from above of a foot-step bearing with radial and thrust ball bearings, suitable for supporting a shaft of diameter 60mm.

Fig. 1.2 Foot-step bearing

Collar thrust bearing

This is generally used for supporting a horizontal shaft under axial load. Further, in this, the shaft extends through and beyond the bearing. The shaft in a collar thrust bearing may consists of one or more collars which are either fitted to or integral with the shaft (Fig. 1.3). The collars rotate against the stationary split bearing surfaces.



Fig. 1.3 (*a*) Single collar bearing,

(b) Multi-collar bearing

Week-X Assembly Drawings

ENGINE PARTS

Assembly of Stuffing Box

It is used to prevent loss of fluid such as steam, between sliding or turning parts of machine elements. In a steam engine, when the piston rod reciprocates through the cylinder cover; stuffing box provided in the cylinder cover, prevents leakage of steam from the cylinder.

Figure 1.0 shows the various parts of a stuffing box. At the base of stuffing box body 1, a bush 3 is placed such that the bevelled edge of the bush is at the inner side of the body. Gland 2 is placed at the other end of the body and is connected to the main body by means of studs 4 and nuts

The space between the reciprocating rod and the bush and the gland is packed with a packing material such as mineral fibres, leather, rubber or cork.

Exercise

Assemble all parts of the stuffing box for a vertical steam engine, shown in Fig. 1.0 and draw, (*i*) half sectional view from the front, with left half in section, (*ii*) half sectional view from the right and (*iii*) view from above.

Stuffing Box Assembly



Parts list			
Part No.	Name	Mati	Qty
1	Body	CI	1
2	Gland	Brass	1
3	Bush	Brass	1
4	Stud	MS	2
5	Nut, M12	MS	2











	/		
Parts list			
Part No.	Name	Matl	Qty
1	Body	CI	1
2	Gland	Brass	1
3	Bush	Brass	1
4	Stud	MS	2
5	Nut, M12	MS	2





Exercise No. 35 Assembly of Connecting Rod

Exercise No. 36 Assembly of eccentric

The details of an eccentric are shown in **Fig. 2.** Assemble the parts and draw, (*i*) half sectional view from the front, with top half in section, (*ii*) view from the right and (*iii*) view from above.



Assembly Model of an Eccentric



Assembly Drawing of an Eccentric









φ70

φ50

φ66

φ100

¢100

φ140

(1)





(5)

Parts list Part No. Name Matl Qty Body CI 1 1 2 Nut GM 1 3 Screw MS 1 4 CS 1 Cup 5 Washer MS 1 6 Screw MS 1 7

MS

1

Tommy bar

(6)

Screw Jack Assembly

185



Exercise No. 38

Assembly of Machine vice



Assembly Drawing :







Tail Stock Assembly



Exercise No.40 Assembly of Ramsbottom Safety Valve



Assembly Of Ramsbottom Safety Valve



Exercise No.41 Assembly of Feed Check Valve



Feed Check Valve Assembly

